

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Representatives Present During the Inspection:

OGM Karl Houskeeper

## **Inspection Report**

Permit Number:	C0070019
Inspection Type:	PARTIAL
Inspection Date:	Thursday, January 27, 2011
Start Date/Time:	1/27/2011 8:30:00 AM
End Date/Time:	1/27/2011 12:00:00 PM
Last Inspection:	Monday, December 06, 2010

Inspector: Karl Houskeeper,

Weather: Partly Cloudy, Temp. 27 Deg. F
InspectionID Report Number: 2634

Accepted by: jhelfric 2/3/2011

Permitee: ANDALEX RESOURCES INC Operator: ANDALEX RESOURCES INC

Site: CENTENNIAL MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

Total Permitted	6,528.83	
Total Disturbed	47.19	
Phase I		
Phase II		
Phase III		

Mineral Ownership

Types of Operations

✓ Federal
✓ Underground

✓ State
Surface

County
Loadout

✓ Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Checked in at the main office located at the West Ridge Mine before preforming the inspection.

Inspector's Signature:

Harl A. Doubages

Date

Thursday, Januan NR<sup>011</sup>

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Thursday, January 27, 2011

Page 2 of 3

## REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
   Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		<b>Y</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations	✓	<b>✓</b>		
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	✓	<b>✓</b>		
7.	Coal Mine Waste, Refuse Piles, Impoundments	<b>Y</b>	<b>✓</b>		· []
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit			. 🔲	
21.	Bonding and Insurance				
22.	Other				

**Inspection Continuation Sheet** 

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Thursday, January 27, 2011

Page 3 of 3

## 2. Signs and Markers

The mine identification sign is located along side of the public road and at a point of entrance into the permit area. The sign contains the required information.

## 4.a Hydrologic Balance: Diversions

All Diversions are snow covered.